

Recd

28 JUL 1981

MEMORANDUM FOR: Deputy Director for Administration

FROM: James H. McDonald
Director of Logistics

SUBJECT: Progress Report on the Office of Technical
Service Inspection Report Recommendation 3

REFERENCE: Memo for DDA from DCI, dtd 7 May 81, Same
Subject (DD/A 81-0067/5; OL 1 1995)

1. Attached herewith is a blind memorandum responding to the request of the Deputy Director of Central Intelligence regarding Recommendation 3 of the Inspector General's report.

2. For your information, the Real Estate and Construction Division, OL, and the Logistics Services Division, OL, have been, and will continue, pursuing various actions to improve the habitability and upkeep of the 2430 E Street, Washington, D.C., complex.

25X1

for James H. McDonald

Att

cc: SG/OS

Distribution:

Original - Addressee
✓ 1 - OL/RECD Official
1 - OL/RECD Chrono
1 - OL/RECD/FEB Chrono
1 - D/L Chrono
1 - OL Files

1 - OL/P&PS
1 - OL/LSD

OL/RECD/FEB/

(27 July 81)

STAT

OL 1 1995a

Progress Report on the Office of Technical Service
Inspection Report Recommendation 3

1. The Office of Logistics (OL) has been, and will continue, pursuing various major items with the General Services Administration (GSA) in regards to the 2430 E Street, Washington, D.C., complex. GSA has hired a consulting firm to conduct an independent investigation and make recommendations for improvements. The Real Estate and Construction Division (RECD), OL, has identified to GSA and their consultant specific areas of concern. GSA has advised RECD/OL that it will not implement action on any recommendations until the survey is completed.

2. The Safety Group, Office of Security, has made a draft copy of its occupational safety and health inspection report for the E Street complex available for RECD/OL review. A number of electrical deficiencies, such as improperly grounded outlets, missing junction box covers, etc., have been identified in the safety report. Deficiencies in the fire protection system, such as defective heat detectors, improperly maintained fire extinguishers, etc., were also noted. Corrections to the electrical and fire protection systems, as well as housekeeping needs, will be vigorously pursued by the Logistics Services Division, OL, through the Office of Technical Service and GSA.